

Black Dog Manufacturing

Battery Terminal Repair Kit

**LR3 2005 to 2009 LR4 2010 to 2016 & Range Rover Sport
2010-2013**

When your Positive battery terminal (cup and cone) wears out and no matter how tight you get it just will not tighten down



**Black Dog has the solution for you
Instead of buying a new cable for \$265.00 and 3 hours labor time
you replace just the Terminal Head**

First: Remove battery cover and you will see the Positive terminal and block that houses the 450 amp fuse.



Second: Remove the negative battery terminal and set aside.



Thrid: Remove cables and set aside.



Then cut the head off right at the block.

In the kit you will have a new battery terminal
two copper plates two Allen head studs and two
flanged nuts.



Fouth: Install the two supplied studs
Allen head side up so you can tighten
them down

Fifth: Install the two copper plates chamfer side to the new battery terminal but leave them loose.



now slide the two copper plates over the studs.

and reinstall the other cables



Sixth: Snug down the nuts and tighten the two Allen head screws on the battery terminal and install the new terminal onto the battery post and tighten down.

Seventh: Complete tightening the two flanged nuts, reinstall the negative battery terminal and battery cover and you are finished.